WATER WELLS

Specialist in : Ground Water Exploration, Development, Management and Rejuvenation

GEOLOGICAL - GEOHYDROLOGICAL - GEOPHYSICAL REPORT

V. APRAMEYA MURTHY, B.Sc (HONS), M.Sc
Geologist
Ex-Officio RDPR, Department
744, 7th A Cross, A Sector
Yelahanka New Town, Bangalore - 560 064.

MOB : 94484 19262
RES : 080-28561744

Date : 4-7-2022

1. Name :	AEE BBMP T. Dasarahally Sub-Div Bangalore	
2. Address : Survey No.: T. Dasarahally	Modern Colony Pipe Line Rd	Taluk : Bangalore / Dist : Bangalore
3. Topography of the area.		plain Terrain.
4. Geology of the area.		Gnissic
5. Geohydrological condition of the area		Moderate
6. Survey conducted for	A. Type of Area	Agriland / Site / Layout / PWS.
	B. Purpose	Irrigation / Domestic / Water Supply
7. Method of Survey Employed :		Geological - Geophysical - Geohydrological
8. RECOMMENDATION	A. Type of well	6 1/2" Dia Bore Well
	B. Location	pipe line Road Ayappa Swamy Cholum
	C. Depth	1200 ft
	D. Probable casing	
9. YIELD EXPECTED*		2" to 3"
10. SPECIAL RECOMMENDATION IF ANY		outer P.V.C. Casing may require if caved

*Conditions Apply.

Assistant Executive Engineer
T. Dasarahalli Sub Division
Bagalagunte, BBMP
Bangalore-560073

For WATER WELLS

V. APRAMEYA MURTHY
Geologist

Scanned with OKEN Scanner

WATER WELLS

Specialist in : Ground Water Exploration, Development, Management and Rejuvenation

GEOLOGICAL - GEOHYDROLOGICAL - GEOPHYSICAL REPORT

V. APRAMEYA MURTHY, B.Sc (HONS), M.Sc
Geologist
Ex-Officio RDPR, Department
744, 7th A Cross, A Sector
Yelahanka New Town, Bangalore - 560 064.

MOB : 94484 19262
RES : 080-28561744

Date : 4 - 7 - 2022

1. Name :	AEE BBMP Sub-Dvn T. Dasarahally Bangalore.	
2. Address : Survey No.: T. Dasarahally	Taluk : Bangalore	
	Dist : Bangalore	
3. Topography of the area.	Plain Terrain.	
4. Geology of the area.	Gnissic	
5. Geohydrological condition of the area	Moderate	
6. Survey conducted for	A. Type of Area	Agriland / Site / Layout / PWS
	B. Purpose	Irrigation / Domestic / Water Supply
7. Method of Survey Employed :	Geological - Geophysical - Geohydrological	
8. RECOMMENDATION	A. Type of well	6 1/2" Dia Bore Well
	B. Location	5th Main K.K. Road T. Dasarahally
	C. Depth	1100 ft
	D. Probable casing	120 to 140 ft
9. YIELD EXPECTED	2" +	
10. SPECIAL RECOMMENDATION IF ANY	Outer P.V.C. Casing may Required	

Assistant Executive Engineer
T. Dasarahalli Sub Division
Bagalagunte, BBMP
Bangalore-560073

*Conditions Apply.

For WATER WELLS

V. APRAMEYA MURTHY
Geologist

Scanned with OKEN Scanner

WATER WELLS

Specialist in : Ground Water Exploration, Development, Management and Rejuvenation

GEOLOGICAL - GEOHYDROLOGICAL - GEOPHYSICAL REPORT

V. APRAMEYA MURTHY, B.Sc (HONS), M.Sc
Geologist
Ex-Officio RDPR, Department
744, 7th A Cross, A Sector
Yelahanka New Town, Bangalore - 560 064.

MOB : 94484 19262
RES : 080-28561744

Date : 4-7-2022

1. Name :	AEE BBMP Sub-Dn T. Dasarahally Bangalore		
2. Address : Survey No.: T. Dasarahally		Taluk : Bangalore	
		Dist : Bangalore	
3. Topography of the area.		plain Terrein	
4. Geology of the area.		Gniessic	
5. Geohydrological condition of the area		Modarate	
6. Survey conducted for	A. Type of Area	Agriland / Site / Layout / PWS.	
	B. Purpose	Irrigation / Domestic / Water Supply	
7. Method of Survey Employed :		Geological - Geophysical - Geohydrological	
8. RECOMMENDATION	A. Type of well	$6\frac{1}{2}$" Dia Bore well	
	B. Location	I st Main Nrupathunga Nagar Near Bhyraveshwara Temple	
	C. Depth		
	D. Probable casing		
9. YIELD EXPECTED		3"	
10. SPECIAL RECOMMENDATION IF ANY		outer P.V.C. Casing may Required	

Assistant Executive Engineer
T. Dasarahalli Sub Division
Bangalagunte, BBMP
Bangalore-560073

*Conditions Apply.

For WATER WELLS

V. APRAMEYA MURTHY
Geologist

Scanned with OKEN Scanner